



## PSCAD v5.0.0 Update 1 (v5.0.0.1)

The updates below are included in PSCAD v5.0.0 Update 1 (February 19, 2021).

### EMTDC

1. An initialization error was resolved in IEEE AC exciter (excac\_2016) (Bug #8703)
2. An initialization error was resolved in IEEE ST exciter (excst\_2016) (Bug #8709)

### Master Library v5.0.0.1 (February 12, 2021)

1. A parameter that was wrongly disabled was re-enabled in the multiple run (mrun) component (Bug #8702)

### Master Library v5.0.0.2 (February 17, 2021)

1. Parameter substitution errors were resolved in IEEE AC exciter (excac\_2016) component (Bug #8708)
2. A parameter substitution error was resolved in IEEE ST exciter (excst\_2016) component (Bug #8709)